ocope of	Work for Property Lo					1644 North 32n	<u>a Street</u>		
	Property is: Single Far	nily 🖸	7	Duple	Χ	☐ Other ☐			
Date:	9/8/2015	_							
ake no respo	minimum requirement to meet honsibility for problems discovered by private lenders, insurance co	after the i	insp	pection o	dat	te, or for omissions throu	ugh error or ove		
Exterior	Condition Report								
Location Site	Required Work Landscaping	n/a [7	Yes ☑	1	Note/Comments Self Help		\$	Cost 500.00
Site	Steps/Handrails	n/a	<u></u> 7	Yes [1	Sell Help		\$	300.00
	Service walks	n/a [Yes [1			\$	
	Fencing	n/a	1	Yes [_			\$	500.00
	Parking	n/a [_ Л	Yes [_			\$	
	Retaining walls	n/a √		Yes	1			\$	
	Other	n/a	1	Yes [1			\$	
	Other	n/a [Yes [7			\$	
Garage		_	_		_				
	Singles: repair			Yes L	<u></u>			\$	
	Shingles: Roof over existing	n/a 🕓		Yes L	<u></u>			\$	
	Shingles:Tear off & re-roof	n/a 🕓		Yes L				\$	
	Gutters/downspouts	n/a 🕓		Yes L				\$	
	Flashing	n/a 🕓		Yes L				\$	
	Eaves	n/a 🕓		Yes L				\$	
	Siding	n/a 🕓		Yes L	<u></u>			\$	
	Doors	n/a 🕓		Yes L	<u></u>			\$	
	Windows	n/a L		Yes L				\$	
	Slab		<u>/</u>	Yes _				\$	
	Paint			Yes [\$	
	Electrical Other		<u> </u>	Yes [<u></u>			\$ \$	
Porches	Other	n/a 🕓	<u> </u>	Yes				\$	
	Roof	n/a		Yes 🔽	/			\$	780.00
	Deck-upper	n/a 🕓	/	Yes [\$	
	Decklower	n/a		Yes 🔽	/			\$	2,880.00
	Steps/handrails	n/a		Yes 🗸	/			\$	750.00
	Ceiling	n/a		Yes 🔽	/			\$	480.00
	Guardrails	n/a		Yes 🔽	/			\$	713.00
	Structural	n/a		Yes -	/			\$	760.00
	Paint	n/a		Yes 🗔	/			\$	400.00

n/a 🗌 Yes 🗌

\$

Other

House

Chimney	n/a ☐ Yes ☑	\$ 500.00
Shingles: repair	n/a ☑ Yes 🗌	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 8,750.00
Gutters/downspouts	n/a ☐ Yes ☑	\$ 1,008.00
Flashing	n/a ✓ Yes 🗌	\$
Eaves	n/a ☐ Yes ☑	\$ 400.00
Siding	n/a ☑ Yes 🗌	\$
Storm Doors	n/a ✓ Yes 🗌	\$
Prime ("main") Doors	n/a ☐ Yes ☑	\$ 350.00
Storm Windows	n/a ☑ Yes 🗌	\$
Prime ("main") Windows	n/a ☐ Yes ☑	\$ 3,100.00
Paint	n/a ☑ Yes 🗌	\$
Foundation	n/a ☐ Yes ☑	\$ 1,000.00
Electrical	n/a ✓ Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a ☐ Yes ☐	\$
Other	n/a 🗌 Yes 🗌	\$

Exterior: Estimated Cost:* \$ 22,871.00

 $\mbox{\ensuremath{^{\star}}}\mbox{average contracted cost.}$ Actual costs may vary. Self help will reduce the amount.

Mechanical	Ondition Report Unit: Entire unit (single family) Upper unit of duplex Required Work	✓ □		Lower unit of duplex Other	
Heating	Repair/replace boiler	n/a ✓	Yes 🗌		\$
	Repair radiation	n/a 🗸	Yes 🗌		\$
	Repair/replace furnace	n/a	Yes 🗸		\$ 3,080.00
	Repair ductwork	n/a	Yes 🗸		\$ 500.00
	Replace thermostat	n/a 🗌	Yes ✓		\$ 100.00
	Repair/replace grilles	n/a 🗸	Yes 🗌		\$
Electrical	Tune boiler/furn. insp ht exchange	n/a ☑	Yes 🗌		\$
Electrical	Repair/replace receptacles	n/a 🗌	Yes ✓		\$ 547.00
	Repair/replace switches	n/a	Yes ✓		\$ 232.00
	Repair/replace fixtures	n/a	Yes ✓		\$ 312.00
	Install outlets and circuits	n/a ✓	Yes 🗌		\$
	Install outlets and circuits	n/a ✓	Yes 🗌		\$
	Install outlets and circuits	n/a ✓	Yes 🗌		\$
	Install outlets and circuits	n/a ✓	Yes 🗌		\$
	Upgrade service	n/a	Yes 🗸		\$ 1,796.00
	Other	n/a	Yes 🗸	Permit Required	\$ 85.00
Plumbing	Other	n/a 🗌	Yes		\$
i iuiiibiiig	Repair/replace kitchen sink	n/a 🗌	Yes 🗌		\$
	Repair/replace kitchen sink fauce	en/a	Yes 🗌		\$
	Repair/replace tub	n/a	Yes 🗌		\$
	Repair/replace tub faucet	n/a	Yes 🗌		\$
	Repair/replace toilet	n/a	Yes 🗌		\$
	Repair/replace lavatory	n/a	Yes 🗌		\$
	Repair/replace lavatory faucet	n/a	Yes 🗌		\$
	Repair/replace wash tub	n/a	Yes 🗸		\$ 700.00
	Repair/replace wash tub faucet	n/a	Yes ✓		\$ 350.00
	Other	n/a	Yes ✓	Complete Bath	\$ 2,170.00
	Repair drain/waste/vent piping	n/a	Yes 🗸		\$ 300.00
	Repair water piping	n/a	Yes 🗸		\$ 300.00
	Repair/replace water heater	n/a	Yes ✓		\$ 1,300.00
	Other	n/a	Yes 🗸	Complete Kitchen	\$ 1,455.00

n/a 🗌 Yes 🗸 Permit Required

Other

85.00

Windows											
	Replace broken glass	n/a	V	Yes			\$				
	Repair or replace sash	n/a	V	Yes			\$				
Doors											
	Repair or replace doors	n/a		Yes	V		\$	380.00			
	Repair or repl. locks/latches	n/a		Yes	✓	Self Help	\$	110.00			
Walls/Ceiling	-		_		_		_				
	Repair or repl. @ defective	n/a	Ш	Yes	1		\$	1,600.00			
Paint											
	Repair or repl. @ defective	n/a		Yes	V		\$	800.00			
Fire Safety											
	Install smoke/CO alarm:bsmt.	n/a		Yes	✓	Self Help	\$	60.00			
	Install smoke/CO alarm: 1st flr.	n/a		Yes	√	Self Help	\$	60.00			
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	V	Self Help	\$	60.00			
Handrails	Repair/replace defective	n/a	П	Yes	7	Self Help	\$	124.00			
Stairs						·					
	Repair defective	n/a		Yes	J		\$	450.00			
Floors	Repair defective	n/a		Yes	7		\$	2,100.00			
Other	Repail defective	II/a		163	<u> </u>		Ψ	2,100.00			
		n/a		Yes	V	2 basement glass block windows W/vents	\$	450.00			
		n/a		Yes			\$				
		n/a		Yes			\$				
		n/a		Yes			\$				
						Interior: Estimated Cost:	\$	19,506.00			
						Total Exterior and Interior Cost:*	\$	42,377.00			
						*average contracted cost. Actual costs may vary. Self help will reduce the amount.					

Date: 9/8/2015 Inspected by Eric Yanke

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.